



URGENT Medical Device Correction

Trilogy EV300, Trilogy Evo O₂, Trilogy Evo Universal
Accuracy of FiO₂ Delivery

01 MAR 2023

This document contains important information for the continued safe and proper use of your equipment.

Please review the following information with all members of your staff who need to be aware of the contents of this communication. It is important to understand the implications of this communication.

A problem has been identified within the Philips Respironics Trilogy EV300, Trilogy Evo O₂, and Trilogy Evo Universal ventilators that could pose a risk for patients if not mitigated. This URGENT Medical Device Correction Letter is intended to inform you of the problem. Please note, these devices can continue to be safely used in line with the mitigations described within as well as in accordance with the Instructions for Use.

1. Description of the issue

Philips Respironics has discovered, through internal testing, that accuracy of **delivered** oxygen may deviate below the required tolerance of 5% from **setpoint** when providing high concentration oxygen therapy. Additionally, if equipped, the internal FiO₂ sensor may indicate a value higher than the device is actually delivering. This may vary based on the patient's lung capacity, lung resistance, use of a particulate filter, or circuit configuration. In the worst case, this may lead to under delivery of oxygen.

2. Potential hazards associated with the issue.

Philips Respironics has assessed the issue and has determined that across the range of tested conditions the following hazard could be present for the most vulnerable patient populations that use these devices. If actual oxygen delivery deviates from the prescribed concentration, beyond the labeled tolerance of 5%, and the patient is not appropriately monitored, the patient may experience oxygen desaturation or hypoxemia.

The potential for this hazard is most likely to occur when the Trilogy EV300, Trilogy Evo O₂, or Trilogy Evo Universal high pressure oxygen blending module (OBM) is used to manage patients requiring high volumes of oxygen such as scenarios requiring **FiO₂ setpoint greater than or equal to 70%**.

3. Affected products and how to identify them.

All distributed Trilogy EV300, Trilogy Evo O₂, and Trilogy Evo Universal devices are impacted by this issue. Each of these devices can use oxygen blending hardware to incorporate externally supplied high-pressure oxygen with ventilated air for high concentration oxygen (FiO₂) therapy.

Trilogy Evo, which is not configured with a high-pressure oxygen blending module (OBM), is **not impacted by FiO₂ under delivery**.

To identify the model, refer to the part number on the bottom of the device with the attached list of impacted part numbers:



4. Actions that should be taken by the user in order to prevent risks for patients.

Until a solution is provided by Philips Respironics, patients prescribed Trilogy EV300, Trilogy Evo O₂, or Trilogy Evo Universal that use high pressure oxygen, the following precautions must be observed:

1. Continuously monitor oximetry (SpO₂) of the patient and follow your institution's protocol for monitoring of arterial blood gas measurements to ensure that the patient is receiving adequate oxygenation.
2. Use an external FiO₂ monitor for any patient requiring **FiO₂ ≥70%** to identify under delivery of oxygen. Switch to an alternative ventilator if an external FiO₂ monitor is not available.
3. Maintain an immediately available back-up device that will allow rapid transition to a different oxygen delivery method or alternative ventilator if monitoring suggests FiO₂ is not being sufficiently delivered.

Distribute this notice to all employees in your organization that need to be aware.



5. Actions planned by Philips Respironics to correct the problem.

Philips Respironics will release a software update that will address the issue. This software will be available free of charge to all Trilogy EV300, Trilogy Evo O₂, and Trilogy Evo Universal users. Additional details will be provided when the update is available. In the interim, please take the actions above in order to prevent risk for your patients.

If you need any further information or support concerning this issue, please contact your local Philips representative or Philips Respironics Customer Service at 1 (800) 345-6443.

This notice has been reported to the appropriate Regulatory Agencies. Adverse reactions or quality problems experienced with the use of this product may be reported to the FDA's MedWatch Adverse Event Reporting program either online, or by regular mail, or by fax.

Philips regrets any inconvenience caused by this problem.

Sincerely,

A handwritten signature in black ink, appearing to read "Tom Fallon".

Tom Fallon
Head of Quality – Philips Respironics



Impacted Devices Models

Part Number	Description
DS2200X11B	Trilogy Evo, O2, USA EV300
DS2100X11B	Trilogy Evo, O2, USA
DS2000X11B	Trilogy Evo Universal Ventilator
IN2100X15B	Trilogy Evo, O2, International
IN2100X19	Trilogy Evo, O2, International (Non-BT)